HARKEN[®]

391 Hook-In Sprit Halyard Block

N15W24983 Bluemound Rd., Pewaukee, WI 53072-4974 USA Telephone: (262) 691-3320 • Fax: (262) 691-3008 Web: http://www.harken.com • Email: harken@harken.com

Installing Plastic Mast Guard

Use rubbing alcohol to remove residue from mast.

Remove blue backing from mast guard and place below mounting hole.



Maintenance

Harken equipment requires minimal maintenance, but some is required to give the best service and to comply with Harken's limited warranty.

It is important to keep equipment clean by frequently flushing with fresh water. In corrosive atmospheres, stainless parts may show discoloration around holes, rivets and screws. This is not serious and may be removed with a fine abrasive.

Important! Exposure to some teak cleaners and other caustic solutions can result in discoloration of part and is not covered under the Harken warranty.

Warranty

For additional safety, maintenance and warranty information see www.harken.com/manuals or the Harken® catalog.